



PHOTOGRAPH 1 of 14: Plant 1 Visitor Entrance Parking Lot facing south (Date and Time on Photograph)



PHOTOGRAPH 2 of 14: Plant 1 Solvent Room with hazardous waste storage totes facing northeast (Date and Time on Photograph)



PHOTOGRAPH 1 of 14: Plant 1 Visitor Entrance Parking Lot facing south (Date and Time on Photograph)




PHOTOGRAPH 2 of 14: Plant 1 Solvent Room with hazardous waste storage totes facing northeast (Date and Time on Photograph)

FICOSA North America Corporation - EPA ID: IND 152 719 878
Photographer D. Sharrow with Nikon Cool pix digital camera, with 8.1 megapixel resolution.



PHOTOGRAPH 3 of 14: Plant 1 Solvent Room with close-up of label on hazardous waste storage tote facing northeast (Date and Time on Photograph)



PHOTOGRAPH 4 of 14: Plant 1 Satellite Accumulation Area signage (Date and Time on Photograph)



PHOTOGRAPH 5 of 14: Plant 1 Satellite Accumulation Area Containers and labels (Date and Time on Photograph)




PHOTOGRAPH 6 of 14: Plant 1 Universal Waste and Used Oil Storage Area facing west to southwest (Date and Time on Photograph)



PHOTOGRAPH 7 of 14: Plant 1 Universal Waste and Used Oil Storage Area facing southeast (Date and Time on Photograph)



PHOTOGRAPH 8 of 14: Plant 1-90 Day Storage Area - 2 Used Oil Containers facing southeast (Date and Time on Photograph)



PHOTOGRAPH 9 of 14: Plant 1-90 Day Storage Area - 2 Non-Hazardous Waste Containers facing south (Date and Time on Photograph)




PHOTOGRAPH 10 of 14: Plant 1-90 day storage area -3 hazardous waste storage drums facing north (Date and Time on Photograph)




PHOTOGRAPH 11 of 14: Plant 1-90 day storage area -3 hazardous waste storage drums facing north (Date and Time on Photograph)



PHOTOGRAPH 12 of 14: Plant 1-90 day storage area -4 non-hazardous waste storage drums facing south (Date and Time on Photograph)



PHOTOGRAPH 13 of 14: Plant 1 – 90 day storage area – exterior gate and signage facing north (Date and Time on Photograph)



PHOTOGRAPH 14 of 14: Plant 2 – 1 Satellite Accumulations and 1 Product Drum facing south (Date and Time on Photograph)